Attachment 5

Description of City-Funded Work for the Bashor Residence

| | | Estimated | Amount |
|-------|---|--------------|-------------|
| Phase | Description of City-Funded Work | Cost | Allocated |
| | Paint: surface preparation; abatement of | | |
| 1 | lead paint; application of 2-3 coats of paint | | |
| | to all wood elements as directed | \$18,270.00 | \$9,135.00 |
| 2 | Front Verandah Restoration: controlled | | |
| | disassembly and reassembly | \$21,924.00 | \$10,962.00 |
| | Cladding: wood cladding and stone dock | Ψ=1,0=1100 | ψ.ο,οοΞ.οο |
| 3 | Cladding: wood cladding and stone dash | | |
| | cladding - restore and repair as required | \$23,751.00 | \$11,875.50 |
| 4 | Storm Window Renewal: localized | | |
| | repairs, resealing, replacement of | | |
| | bathroom window | \$20,097.00 | \$10,048.50 |
| 5 | Chimney Restoration: repair and | | |
| | repointing as required on two chimneys | \$7,308.00 | \$3,654.00 |
| | Foundation Repair: shoring of foundation | | |
| 6 | with treated lumber and blocking; | | |
| | inspection by engineer | \$11,502.75 | \$5,751.38 |
| 7 | Roof: removal of asphalt roofing; | | |
| | installation of ice and water shield, | | |
| | underlayment, cedar shingles | \$41,578.00 | \$20,789.00 |
| 8 | Contingency: up to 5% of eligible costs | | |
| | Contingency: up to 3% of engible costs | \$7,221.54 | \$2,784.62 |
| | | | |
| | TOTAL | \$151,652.29 | \$75,000.00 |