

Photographs of the Barto Residence



View of west (front) elevation, showing restoration of existing wood cladding.



View of south elevation, showing restoration of existing wood cladding.