

**Description of the City Funded Work on the Restoration of the John Wood Residence**

<b>Phase</b>	<b>Description of City Funded Work</b>	<b>Total Estimated Cost</b>	<b>Amount Allocated</b>
<b>1.</b>	<b>Exterior Restoration:</b> selective demolition and rehabilitation of portions of the chimney, exterior cladding and covered verandah.	\$59,797.50	\$29,898.75
<b>2.</b>	<b>Window Restoration:</b> repair and re-glazing of windows on the north elevation and replacement in kind of windows on the east and west elevations.	\$66,675.00	\$31,188.75
<b>3.</b>	<b>Exterior Painting:</b> stripping, cleaning and re-painting of cladding and trim work	\$27,825.00	\$13,912.50
	<b>Total</b>	<b>\$154,297.50</b>	<b>\$75,000.00</b>